

Fatality Alert



MINE FATALITY – On June 13, 2020, a dragline was found submerged in 25 feet of water where a miner had been using it to remove material from a pond. Divers attempted to locate the dragline operator, and after two days the dragline was extricated from the pond. The victim was recovered from the engine compartment behind the operator's cab.





Best Practices

- Maintain control of operating mobile equipment.
- **Keep all exits clear** in cabs, including alternate and emergency exits, and make sure the doors open freely before beginning work.
- Retrofit older models of equipment with current automatic braking systems.
- Ensure all controls and brakes are set to the appropriate position for the task.

This is the ninth fatality reported in 2020, and the second classified as "Machinery"

The information provided in this notice is based on preliminary data only and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the fatality.