

TAKE CONTROL

*Prevent Serious Injuries
and Fatalities*

Moving machine parts are located throughout aggregate facilities – especially at the plant and on conveyors. Hands, limbs, clothing, and long hair can all get caught in moving machine parts and cause a serious injury or fatality. Be sure to inspect any area you're working and double check that all moving machine parts you could reach are properly guarded.



WHEN WORKING AROUND MOVING MACHINE PARTS

ARE YOU ABOUT TO...

- Do **maintenance on moving machine parts** (e.g., conveyor drives, heads, or tail pulleys)?
- Work in an area where you will be **close to moving machine parts**?



TAKE CONTROL!

IMPLEMENT THESE CRITICAL CONTROLS:

- Ensure all moving machine parts **within 7 feet of a walk or working surface** are properly guarded.
- **Inspect your work area** and double check all moving machine parts are properly guarded (you cannot get your hand around it and reach a moving machine part), secured, and undamaged.
- **Secure guards with materials that can withstand wear, corrosion, vibration, and shock** of normal operations.
- **Never walk on, across, or over** a conveyor.
- **Check emergency stop cords** for proper function and **maintain adequate tension**.