

## Fatality Alert

MINE FATALITY – On April 19, 2021, a miner stopped his haul truck in front of his personal truck to get his lunch. While standing and eating his lunch, the haul truck rolled forward, pinning the miner between the haul truck and his personal truck.



### Best Practices

- **Do not leave mobile equipment unattended** unless the controls are placed in the park position and the brake is set. NEVER use a steering column-mounted "dump brake" for parking.
- **When parking mobile equipment on a grade, chock the wheels or turn them into a bank.** Maintain equipment braking systems in good repair and adjustment.
- **Position yourself in a safe location** away from potential “danger-zone” areas.
- **Train miners** to safely perform their tasks.

This is the eighth fatality reported in 2021, and the fourth classified as “Powered Haulage.”

---

The information provided in this notice is based on preliminary data only and does not represent final determinations regarding the nature of the incident or conclusions regarding the cause of the fatality.

**Report accidents and hazardous conditions: 1-800-746-1553**

[msha.gov](https://www.msha.gov) | [askmsha@dol.gov](mailto:askmsha@dol.gov) | [@MSHA\\_DOL](https://twitter.com/MSHA_DOL)